



# **Plutonium Intakes at the Savannah River Site FB-Line on September 1, 1999**

**Chuck Radford, DOE-SR  
Tony Weadock, EH-10**



# **FB-Line Intakes Introduction**

**Subject: Pu-239 Release/Worker Intakes**

**Contractor: Westinghouse Savannah River Company**

**DOE Coord: John Pullen, Mosi Dayani**


**EH-10 Lead: Tony Weadock**



# Event Overview

- ◆ **Defective weld on plutonium storage can led to FB Line Pu-239 release on 9/1/99. Seven workers were working in vault/vestibule preparing cans for transport.**
- ◆ **Eight workers (one cross-contamination) received intakes; one in excess of annual limits**
- ◆ **Type B Investigation conducted by DOE-SR; report issued 2/2000 ([http://tis.eh.doe.gov/oversight/acc\\_inv/acc\\_investigations2.html](http://tis.eh.doe.gov/oversight/acc_inv/acc_investigations2.html))**
- ◆ **EH-Enforcement investigation conducted 4/2000**
- ◆ **EA -2000-08 issued 7/2000; PNOV and 220K civil penalty**

# Diagram of Vault/Vestibule Area





# Event Timeline

- ◆ Bagless Transfer Can welded on July 14, 1998, with defect

- ◆ Can passed visual inspection and leak checks (gross and helium).
- ◆ Can placed in vault on July 14, 1998, and not disturbed (moved or inspected) until September 1, 1999.

- ◆ Vault evolution on September 1, 1999, considered routine, low hazard work

- ◆ Packaging Bagless Transfer Cans in 6M Containers (30 gallon drum) for shipment to 235-F.
- ◆ Job had been performed several times without incident.

# **Event Timeline (Continued)**

- ◆ **Pre-job brief conducted at 0830 on 9/1/99.**
- ◆ **Personnel proceed to vault at 0945**
  - ◆ **PPE: Personnel in vestibule wore full set of protective clothing or lab coat; personnel entering vault wore full set of protective clothing and respirator.**
- ◆ **Radcon surveys vault to identify any unusual conditions. Fails to survey racks and does not establish dose rate at the door.**



# Event Timeline (Continued)

- ◆ Ops successfully packages two 6M containers, containing two Bagless Transfer Cans each, for shipment to 235-F. Initiates packaging of third 6M.
- ◆ Ops retrieves faulty can from vault and places on masselin cloth in vestibule
  - ◆ RWP requires can be surveyed prior to handling by ops.
  - ◆ Faulty can brought into vestibule for survey. Should have been surveyed in vault.

# Event Timeline (Continued)

- ◆ Radcon surveys show 2000 dpm alpha/100cm<sup>2</sup> on can. Ops begins can decon in vault
  - ◆ RWP vestibule contamination suspension limit of  $\geq 2000$  dpm alpha/100cm<sup>2</sup>. Evolution should have stopped immediately.
- ◆ HVAM alarm sounds as Ops begins to decon. Ops returns can to rack and exits vault, pushing vault door closed
  - ◆ Radcon should have surveyed operator immediately after exiting vault



# Event Timeline (Continued)

- ◆ Radcon inspectors response to alarm.
  - ◆ Per interview, initially felt alarm was an electrical spike. Made several calls to verify, instead of surveying HVAM planchet.
  - ◆ Began surveys in vestibule.
- ◆ Operations discusses requirement to secure the vault
  - ◆ MC&A/requirements not addressed in procedure.
  - ◆ Ops FLS not knowledgeable of MC&A requirements under abnormal conditions.
  - ◆ Confusion as to meaning of “secure the vault”.

## **Event Timeline (Continued)**

- ◆ **Radcon removes planchet from HVAM.  
Survey finds 80,000 dpm alpha.**
- ◆ **Radcon finds contamination in vestibule.  
Surveys motor air pump filter and measures  
80,000 dpm alpha**
- ◆ **Radcon did not notify ops or security of  
airborne contamination levels in the  
vestibule.**



# Event Timeline (Continued)

- ◆ Ops makes decision to reenter vault and secure rack and vault
  - ◆ Enters without knowledge or permission of Radcon.
  - ◆ Enters an airborne radioactivity area without an understanding of whether PPE (full face respirator) would provide adequate protection.
- ◆ Radcon tells ops they need to leave the vestibule, 18 minutes after alarm
  - ◆ No sense of urgency, don't crash out.
  - ◆ All individuals exited in close proximity, creating opportunity for cross-contamination.
- ◆ Eight intakes (original seven and one cross-contamination) and multiple contaminations (skin or effects) resulted from event.

# Bagless Transfer System

## Purpose

- ◆ To remove plutonium from glovebox and seal it in a welded stainless steel can without contaminating outside of the can.


## Process

- ◆ Insert new canister into glovebox, displacing previous canister from sphincter seal.
- ◆ Place plutonium into canister & backfill with Helium.
- ◆ Insert plug into canister and weld plug to canister, applying three tack welds and overpass weld.
- ◆ Cut container in center of the weld.
- ◆ Leave upper portion of canister in sphincter seal to maintain glovebox integrity & remove welded canister containing plutonium.
- ◆ Weld visually inspected by Operator.
- ◆ Volumetric and Helium leak check performed by Operator.






# Bagless Transfer System Overview

## BAGLESS TRANSFER PROCESS



## BAGLESS TRANSFER PROCESS: Weld Explanation



# Weld Defect Failure Analysis

**Failure analysis performed by SRTC with oversight by three outside consultants and AI Board**

## **Process**

- ◆ **Hole in weld existed at completion of weld.**
- ◆ **Oval-shaped hole with ~0.1 inch diameter in can weld at second tack weld.**
- ◆ **A lump of excess material was adjacent to hole.**
- ◆ **No deviations from specifications found in canister chemical composition, dimensions or cleanliness.**
- ◆ **Appearance of weld hole consistent with blow-out during welding.**
- ◆ **SRTC could not conclusively determine exact cause of weld failure.**
- ◆ **Most likely cause – overpressurization of can during welding (possibly due to lack of venting).**



# Weld Integrity Checks

- ◆ Weld defect was created at time of welding and should have been detected.
- ◆ Board considered potential failure mechanisms of weld checks
  - ◆ Human Factors
    - ◆ Weld checks not performed.
    - ◆ View of weld obstructed.
    - ◆ Operator distracted by plant operation/events during checks.
    - ◆ Incorrect operation of leak check equipment.
    - ◆ Miscommunication between Operator and Recorder.
  - ◆ Quality Assurance
    - ◆ Inadequate Operator training for weld inspection/testing.
    - ◆ Inadequate maintenance & calibration of leak test equipment.
  - ◆ Failure of leak test equipment
    - ◆ Board could not conclusively determine reason weld inspection & leak checks failed to detect weld defect.



# Picture of Failed Bagless Transfer Can





# Internal Dosimetry Results

- ◆ Intakes occurred on September 1, 1999.
- ◆ Intakes occurred through inhalation.
- ◆ WSRC Dose Assessment
  - Thirteen individuals placed on special bioassay program as a result of the event.
  - Preliminary and final 50 Year committed effective dose equivalent (CEDE) for 4 individuals:

September 9, 1999		January 4, 2000
Preliminary CEDE (rem)		Final CEDE (rem)
– OPS1	8.8 rem	1.5 rem
– OPS2	16.1 rem	6.7 rem
– OPS5	5.4 rem	2.0 rem
– RC01	2.0 rem	1.6 rem

# Internal Dosimetry Results

## (Continued)

### ◆ WSRC Dose Assessment

- Subsequent to issuance of the Accident Investigation Report, WSRC completed dose assessments for the remaining four individuals identified as having intakes of radioactive material:

	CEDE (mrem)
• OPS3	667
• OPS4	732
• RCO2	702
• WSI1	<10





# Causal Factors

- ◆ **Quality Assurance**
- ◆ **Integrated Safety Management**
- ◆ **Verbatim Procedure Compliance**
- ◆ **Ventilation System**
- ◆ **HVAM Alarm Response**
- ◆ **Radiological Work Practices**
- ◆ **Abnormal MC&A Response**
- ◆ **Security Post Orders**
- ◆ **Pre-Job Briefs**
- ◆ **Command and Control**
- ◆ **HVAM Operation**

# Causes

## Direct Cause

- ◆ Release of Pu from a defective bagless transfer can that resulted in inhalation by FB-Line workers.

## Root Causes

- ◆ Quality Assurance on the bagless transfer can was not adequate to identify the weld defect.
- ◆ Implementation of Integrated Safety Management for plutonium vault operations was inadequate to provide worker protection during interim plutonium storage and handling. Deficiencies noted in all ISM core function areas.



# Type B Conclusions

- ◆ **Type B Board identified that indicators of existing problems were available to WSRC management for an extended time, and should have enabled implementation of effective corrective actions:**
  - **Previous 1996 F-Canyon intake event involved common failures in procedural compliance, lack of surveys, lack of hazard analysis**
  - **Assessment history at FB-Line indicated continuing problems in radiological controls area. Consistently rated as “below average” by Facility Evaluation Board.**
- ◆ **Type B Report identified 16 Judgements of Need to address conclusions reached by Board.**

# Key Factors in Enforcement Decision

- ◆ **Significance**
  - **High - one overexposure, multiple intakes, could have been much worse**
- ◆ **Identification**
  - **Noncompliance conditions disclosed by event**
  - **Assessment history indicated continuing and similar problems in radcon practices**
  - **Prior can weld defects not formally analyzed**
- ◆ **Internal Investigation**
  - **Both WSRC and DOE-SR investigations found to be comprehensive, thorough, largely consistent in conclusions**



# **Key Factors (Continued)**

## **◆ Corrective Actions**

- Corrective actions viewed as broad in scope, with focus on applying lessons learned at both the facility and site level**

## **◆ Prior History**

- Severity Level II PNOV in December, 1997 for radiation protection violations resulting in a worker overexposure in 1996**
- Both WSRC and DOE-SR's investigations noted similar performance failures between current and previous events**

# Enforcement Outcome

- ◆ **PNOV issued July, 2000, with associated civil penalty**
- ◆ **Number of apparent violations; consensus to focus on key areas of concern**
- ◆ **Overexposure (Severity Level II)**
- ◆ **Quality Improvement (Severity Level II)**
  - **Effective processes not in place to ensure weld integrity on bagless cans**
  - **Management processes not effectively implemented to correct identified and long-standing deficiencies in radiological controls**



# **Enforcement Outcome**

## **(Continued)**

- ◆ **Monitoring of individuals and areas (Severity Level II)**
  - **Contamination survey not performed prior to operator handling of bagless cans**
  - **Personnel contamination surveys not immediately performed upon operator exit from vault - no controls established to prevent cross-contamination**
- ◆ **Work Processes (Severity Level II ) - Multiple examples in which procedure not followed (RWP suspension limits, notifications, RCO supervisory approval for entry after CAM, etc.)**

# **Enforcement Outcome**

## **(Continued)**

- ◆ **Design and Control (Severity Level III) - Management did not ensure effective physical design features in place. Deficiencies with vault ventilation were well-known and long-standing; compensatory actions were not taken.**
- ◆ **Base civil penalty would be \$275,000**
  - **No mitigation for identification/reporting**
  - **25% mitigation for four of the violations, based on comprehensive investigation and corrective actions**
  - **No mitigation for overexposure citation**
- ◆ **Civil Penalty of \$220,000 - uncontested**